



MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
May 12, 20008

Supervisor 722

Mine Name: Haas Limestone-Gunnison
Operator Name: Bryce Haas.

Permit number: S/039/0012
Inspection Date: April 29, 2008
Time: 11:45 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Bryce Haas
Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Routine inspection while in the area.

While this site is listed as 'inactive', there has been recent reclamation activity being performed at the site. The large piles of overburden that existed on the eastern (uphill) side of this quarry have been pushed down to fill a portion of the pit. There is still some material that needs to be moved in this area. About 1/2 of the overburden/waste dump along the western edge has been pulled up (regraded) and the material placed in the pit. Even though the agreed upon work has not yet been completed, significant progress has been made. Mr. Haas indicated that because of equipment breakdown he had not been able to complete as much of the reclamation as he wanted to.

Photos were taken to document site conditions.

Continue to monitor this site when in the area.

O:\M039-Sanpete\S0390012-HaasLimestone-gunnison\inspections\Insp-04292008.doc

080002